

BANGOR

MARINA

Notice to Mariners

No 1 of 2024

Eisenhower Pier Navigational Beacon - ISO R 12S 9M

In Position 54° 40' 1.92" N 5° 40' 19.56" W



Mariners are advised that this aid to navigation is not operational.

This fault will be repaired or the light will be replaced as soon as possible.

Kevin Baird

Harbour Master (Bangor) Issued: Monday 29th January 2024